





*SS. No. 427 now partly held*

N.B.—If this Report is copied by copying Press, especial care must be taken that the copying razer is not so much damaged as to spread the ink, or to cause it to show through to the other side.

*by examination of propeller,  
sea connections & fastenings.*

*It is submitted that  
this vessel is eligible to  
be entered in the Lloyd's Register.*

*Note the above as part*

*SS. No. 427.*

*254.  
11/3/27.*

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THE MARGIN.



© 2020

Lloyd's Register  
Foundation