

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 19... When handed in at Local Office 19... Port of London

No. in Reg. Book. 35467 Survey held at Hamburg Date, First Survey Last Survey 19

TONNAGE: Built at HAVERTON HILL on TEES By whom FURNESS S.B. CO. LD. When 1920 12
GROSS 5453 Owners HAMBURG-BREMER AFRIKA-LINIE Owners' Address
UNDER DK. 5161 Managers WOERMANN-LINIE A.G. DEUTSCHE OST Port belonging to BREMEN.
NET 3287 AFRIKA-LINIE.

Surveyed Afloat or in Dry Dock? Name of Dock Destined Voyage
WB=Cell D for DBa feet; uE&B feet; f feet
total capacity tons. FPT tons; APT tons; MT feet tons.

N.B.—All alterations in the existing records should be underlined.
If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, keel, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 1655 Port Rinn

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.)

CHARACTER	Year	Month
100 A 1	1933	12
Shelter dks with freeboard	BS	10, 34
10, 33	CL	12, 32
ss. Kel. No. 3-10, 29		
ss. Bmn. No. 1-33		
Pitted for Oil Fuel 12, 20		
Flash Point above 150° F.		

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Society's Freeboard (if assigned) as painted on Ship and now verified

Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

SUMMARY OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

PRESENT CONDITION OF THE	State if Tanks have been examined inside	Air and Sounding Pipes	Copper, or Y.M. of Wood Vessels
Decks	State if Tanks now tested	Dbing. Plates under Sounding Pipes	(State if on felt). When put on, Month Year
Caulking of Decks	Bulkheads	Engine Room Skylights	Boats
Coamings	Ceiling	Coal Bunkers, Open'gs, Lids, &c.	Masts, Yards, &c.
Beams & Fastenings	Cement or Asphalt (State which.)	Oil Bunkers	Condition, how ascertained
Outside Plating	Rudder	Scuppers	(State if wedges removed)
" " in way of sidelights	Steering gear and its connections	Cargo Hatchways	Sails
Breasthooks	Windlass	Hatches	Equipment letter
Transoms	Have pumps now been examined and found efficient?	Planking of Wood Vessels	Anchors, No. of
Frames	Have Sluice Valves now been examined and found efficient?	Caulking ditto	Chain Locker
Reverse Frames	Have Watertight Doors now been examined and found efficient?	Treenails ditto	Cables (State if now ranged)
Longitudinals	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stenson ditto	" length mean diamr.
Transverses		Transoms Pointers, & Crutches ditto	" Rule length size
Floors		Timbers of Frame at openings ditto	Hawser & Warps
Keelsons		Ditto Ditto at other places ditto	Standing and Running Rigging
Stringers		Stringers, Clamps & Shells ditto	
Inner Bottom Plating		Salting ditto (State if examined.)	

General Observations, Opinion as to Class, Recommendation, &c.:—
State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,24," or "to remain as classed and to have record of survey, 1,24, and the notations of ss No. 1-24 and ptND24, &c."

Survey Fee (per Section 29)	Special Damage or Repair Fee (if any) (per Sec. 29)	Travelling Expenses (if chargeable)	Second Surveyor's Fee (if any)	Fees applied for
£	£	£	£	19
				Received by me, 19

Surveyor to Lloyd's Register of Shipping.

Committee's Minute TUE. 3 MAR 1936
Character Assigned Withdraw class
write own & insert Ham (copy)
General Committee Thursday 5th March 1936
Classing Committee's decision confirmed
Lloyd's Register Foundation
W1289-0006



MAR 1936

DISCLOSED BOX No. 143

Is Certificate required? If so, to be sent to