


S.S. Helle

Oslø 4050.

Before this case receives consideration it is submitted the Surveyor be asked to state whether the (original) intermediate + thrust shafting and the condenser have been examined at this time; and that Superheaters have been fitted + tested in accordance with the approved plans.

Classed 20/5/33



C. W. F.
30.5.33

© 2021

Lloyd's Register
Foundation

W1293 - 0150