

12 AUG 1935

Steam Trawler "JUAN"

This case is fully stated in endorsement dated 8.8.35 when the Owners were informed that the Committee had given instructions for the class to be withdrawn from the Register Book and three dots (...) inserted in lieu thereof.

A letter has now been received from the Owner in which he refers to the extensive repairs recently carried out to the vessel at Cadiz. He states that he likes to keep his ships in the Society's class and has only ceased to do so because of the delays occasioned by the surveys, and that the Surveyors do not seem able to attend when required. The vessel will be ready to resume fishing at the end of this week (10th instant) and if the survey would not cause any further delay he would be happy to maintain the classification.

It is submitted that provided a No.3 survey be carried out and the repairs recently effected be found or made satisfactory, the vessel would be eligible to have her class reinstated in the Society's Register Book.

The Cadiz Surveyor should be advised, and he might also be furnished with a copy of the Owner's letter, and asked for his remarks regarding the alleged delays in carrying out surveys.

Two! Shmees
for sufficient

12.8.35



© 2021

Lloyd's Register
Foundation

W1297-0054