

S.S. "PRESIDENT GOMEZ".


(Built 1922).

The weights of the stream and kedge anchors as supplied to this vessel when she was built were under the requirements of the Rules, and the Rotterdam Surveyors stated in November last that new Stream and Kedge Anchors were reported to have been sent to the West Indies to be placed on board.

As the vessel was trading regularly between Curacoaa and Venezuela, Lloyd's Agents at Curacoa were requested to appoint an independent Surveyor to examine the marks on the new stream and kedge anchors on board the vessel, and compare them with the certificates of test, and furnish to this Office a report on such examination on a form which was enclosed.

A Representative of the Owners called at this Office yesterday with reference to this examination.

As kedge anchors are no longer required to be supplied to vessels classed with this Society, it is submitted the Owners might be informed accordingly, and they should be requested to make arrangements for the new stream anchor to be examined at a Port where one of the Society's Surveyors is stationed, at the first convenient opportunity.


25.4.23



© 2020

Lloyd's Register
Foundation

W1298-0121