

S.S. "CAMOSUN"

Q U E R I E S

proposed to be submitted to
MR. GARDINER SMITH, Engineer
Surveyor.

1913.

Wright Johnston & Mackenzie,
Writers, Glasgow.

W1299-0152 1/4



© 2020


Lloyd's Register
Foundation

S.S. "CAMOSUN"

QUERIES proposed to be submitted to MR.

H. GARDINER SMITH, Engineer Surveyor.
=====

- ✓ 1. Had you supervision under construction of the work relating both to machinery and electric light?
- ✓ 2. Did you inspect the engines as the work progressed in the shops and during erection on board the vessel?
- ✓ 3. Were you present at any of the vessel's trials?
If so at which?
- ✓ 4. Were the materials and workmanship used in the engine department in accordance with Lloyd's Rules in every respect?
- 0 5. Were the boiler mountings, valves for feed pump and Salinometer cocks fitted subject to your approval?
- 0 6. Were the joints properly tight between the H.P. and J.P. cylinders?



© 2020

Lloyd's Register
Foundation

W1299-0152/4

✓ 7. Was ample opportunity afforded you by the Builders for thorough examination of materials and workmanship.

0 8. Is it possible that any defects could have escaped your observation.

0 9. Do you think that any part of the materials and workmanship were concealed from you by the builders or their employees?

✓ 10. Was the installation of electric lighting carried out in accordance with Lloyd's requirements? In particular had you any fault to find with the method in which the wires were ^{led} laid or "bunched" together?

✓ 11. Had you any fault to find with the method of insulation or the method of fitting the wires through the cross beams?

0 12. Was there any objection to the wiring being concealed behind the linerusta in the Saloon.

13.



© 2020

Lloyd's Register
Foundation

W1299-0152 3/4

13. Did you observe the wiring and the method of fitting adopted prior to the linerusta being made and shale if you approved of same?
- ✓ 14. In your opinion was there any risk of fire through the method adopted.
- ✓ 15. To your knowledge was anything concealed from you by the builders or any of their employees either in relation to materials or workmanship?
- ✓ 16. In point of fact was every facility not given to you to enable you to carry out your supervision properly.



© 2020

Lloyd's Register
Foundation

W1299-01524/1