

37.83
29.08
8.75

Wreck Section 130

F.E.
(FBD.)

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME "THORNLIEBANK" Rpt. Nwc. No. 97322

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/92.)

1st Long. No.	15760	Depth "d"	24.92
2nd Long. No.	39770	Proportions = $\frac{L}{D}$	11.23 11.02
Framing Bulb angle framing as approved	Sheerstrake		As approved

This vessel is similar to the "TEVIOTBANK".

C.S.S.Vessel with Tonnage Opening.

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed ~~100A1~~ "With Freeboard"

The Summer Freeboard as shown on the attached extract from the Freeboard Verification Form, now marked on the vessel's sides, to be inserted in the classification certificate and recorded in the Register Book, and further, the remaining freeboards, as shown on the accompanying extract, to be inserted in the certificate of classification.

1 Dk. and Shelter Dk. ^{373 1437} Dtd 30' 12 1/2"
Cell.DB 371' 1444t, FPT 149t, APT 227t.

FK, 7BH(Coll.BH to Sh.Dk., 6BH to 2nd Dk.) pt.cem., Lloyd's A & CP.

F 37'

O.L. 451.8'.

[Handwritten signatures]

5:4:39.



© 2019

Lloyd's Register Foundation

W130-0060