

COPY.
PORT OF

30th August 1940.


Messrs. John Readhead & Sons Ltd.,
SOUTH SHIELDS.

Dear Sirs,

Yard No. 518.

Further to our letter of yesterday regarding the omission of hold ceiling, kindly note that the manhole doors in the tank top plating will require to be suitably protected.

Yours faithfully,
THE SURVEYORS,
per


135

© 2019

Lloyd's Register
Foundation

W030 0083