

Less above Crown of } including cushion
Engine Room ... }
TONNAGE FOR FEES.. 7280

Proportions—Depths to Length—Upper Deck Beam at
side to top of keel

15.234

Residence Ham

2,10. LLOYDS REGISTER
LONDON
REC'D APR 2 1912
ANS

Time of Receipt

4' 14

TELEGRAM.

POST OFFICE TELEGRAPHS.
FOR INWARD FOREIGN AND COLONIAL TELEGRAMS.

No. of Telegram. }

Office of Origin.

.+ BREMEN 5+ 86 3 2 4, 17 S

anded in.

Office Stamp.

cd. from

Service Instructions.

Sent or
Sent out at }

To.

By.



= COMMITTEE LONDON = RAWISH .+

Rawish = fees paid today. Forward classification certificate(s)

If the accuracy of this Telegram be doubted, a part, or the whole, can be repeated under special conditions, particulars of which can be
ained on application at the office from which it was delivered.

Charges to pay.

£ s. d.

N.B.—This form must accompany any inquiry made respecting this Telegram.

10) Wt. 12904-1639. 750,000. 7/11. Wy. & S., Ltd. Sch. 35.



© 2020

W1302-0069

Angle, Base, Top Rail, or Channel
Angles on upper edge
Spacing
BEAMS, Third and Fourth Deck, Single Angle,
Bulb Angle, Flange, Top Rail, or Channel

26 1/2
12 6 1/2 .60 12 6 1/2 .60

Deck. Material & thickness.

Poop Deck Stringer Plate, breadth & thickness

Angle on ditto

Tie Plates

in will
49
49 x 48
37 x 44
3 1/2 x 3 1/2
5 x 5

not there
49-37
3 1/2 x 3 1/2

not there
49-37
3 1/2 x 3 1/2
24

61-37
3 1/2 x 3 1/2

Referred to the Chief Ship Surveyor.

F. H. H.

Referred to Mr. Ascough.

Certificates forwarded to
Bureau 7/4/12 D.S. St.

APR. -2 1912



© 2020

Lloyd's Register
Foundation