

Chief Surveyors _____

Received from Chief Surveyors _____

EL'S NAME Non Propelling Steel Barges Hobbs ^{Report} No. 40365 ²³⁴⁰
857 ^{Puerto} Glasgow

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)


e of Survey _____

When due _____

Lloyds Agent at Puerto, Mexico, should be requested to State whether Certificate forwarded by him dated November 30th last, refers to the section of barge N^o 857 or N^o 858 as it accompanied the ^{first} report for the latter vessel. He should also be requested to State on Completion of section whether, the hand pumps have been examined and found efficient, the hatches are strong and efficient, the inner surface of the bottom plating protected by cement and whether the rudder has been shipped. He should further State the date of launch of the vessel.

Mr. 14/1/21

Mr. 14/1/21



HD
© 2020
13-1-21

W1302-0147

Lloyd's Register
Foundation