

the propeller boss

If the liner is in more than one length are the joints burned

If the liner

LOYD'S REGISTER, TRAFFORD ROAD, SALFORD.

W1310-0151

TELEPHONE: TRAFFORD PARK 120.

ications to be addressed  
SURVEYORS.

# Lloyd's Register of Shipping,

162, Trafford Road Salford,

Manchester, 29. May 1920.

LOYD'S REGISTER.  
LONDON.

REC'D MAY 1920

ANSW

The Secretary  
London.

Sir.

With reference to my  
two reports 2<sup>n</sup>. 4591 and 4592 on "A" and "H"  
type Standard engines built by  
Mess<sup>rs</sup>. Cole, Marchant & Morley of Bradford  
and Mess<sup>rs</sup>. Bover & Doring & Co. of Bradford.  
I understand that these two sets  
have been taken over (completed) by  
Mess<sup>rs</sup>. James Howden & Co. of Glasgow  
with the view of disposing of same;  
these were originally intended as  
"Spare Sets".

At present these engines are being  
dismantled ~~and~~ and in all probability  
they will be placed in store in Bradford  
until something definite is arranged.

Yours faithfully  
A. Campbell

meter of tubes

Pitch of tubes

Material of tube plates

Thickness: Front

Back



Referred to the Chief Engineer, Surveyor.

31 MAY 1920



© 2021

Lloyd's Register  
Foundation