

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report

When handed in at Local Office

10

Port of

London

No. in
Reg. Book.

Survey held at

Date, First Survey

Last Survey

19

32751 on the Wood, Iron or Steel

Ronsan Maru

(No. of Visits)

TONNAGE:-

Built at

Tama

By whom

Mitani Bussan Kaisha

YEAR.

MONTH.

1929

9

GROSS

2735

Owners

Dairin Kain K.K.

Owners' Address

(if not already recorded in Appendix to Register Book).

UNDER DK.

2248

Managers

NET

1556

Port belonging to

Nansen

Surveyed Afloat or in Dry Dock?

Name of Dock

Destined Voyage

WB=CellDBorDBa

feet; uE&B

feet; f

feet

total capacity

tons. FPT

tons; APT

tons; MT

feet tons.

Particulars of Classification (which must be inserted
precisely as in Register Book & Supplements)CHARACTER.
* for Special Survey.
Date of last Survey and of
Periodical Surveys.Year
Assigned
how
expired.Machinery and Boiler
Surveys
(including date of N.B., in any).

+100 A1

HMC 05 12.34

7 37

2 37

H In. No 1-34

DBS. 2 37

CL. 12.34

Oil. ENG.

Cargo battens not fitted

Last Report, No.

10281

Port

Kob

(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules and items remaining to complete the Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Society's Freeboard (if assigned) as
painted on Ship and now verified } fl. ins.

Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

OIL F
CONTINUING SURVEY.

SUMMARY OF DAMAGE REPAIRS:-

	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items:-
Renewed								
Removed and Paired or Repaired								
Paired or Repaired in place								

PRESENT CONDITION OF THE

Decks	State if Tanks have been examined inside	Air and Sounding Pipes	Copper, or Y.M. of Wood Vessels (State if on Port.) When put on, Month Year
Caulking of Decks	State if Tanks now tested	Dblng. Plates under Sounding Pipes	Boats
Coamings	Bulkheads	Engine Room Skylights	Masts, Yards, &c.
Beams & Fastenings	Ceiling	Coal Bunkers, Open'gs, Lids, &c.	Condition, how ascertained (State if wedges removed)
Outside Plating	Cement or Asphalt (State which.)	Oil Bunkers	Sails
" " in way of sidelights	Rudder	Scuppers	Equipment letter
Breasthooks	Steering gear and its connections	Cargo Hatchways	Anchors, No. of
Transoms	Windlass	Hatches	Chain Locker
Frames	Have pumps now been examined and found efficient?	Planking of Wood Vessels	Cables (State if now ranged)
Reverse Frames	Have Sluice Valves now been examined and found efficient?	Caulking ditto	" length (on board) mean diamr.
Longitudinals	Have Watertight Doors now been examined and found efficient?	Treenails ditto	" Rule length size
Transverses	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stems ditto	Hawser & Warps
Floors		Transoms Pointers, & Crutches ditto	Standing and Running Rigging
Keelsons		Timbers of Frame at openings ditto	
Stringers		Ditto Ditto at other places ditto	
Inner Bottom Plating		Stringers, Clamps & Shells ditto	
		Salting ditto (State if examined.)	

General Observations, Opinion as to Class, Recommendation, &c.:-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:- "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1.24," or "to remain as classed and to have record of survey, 1.24, and the notations of ss No. 1-24.

Survey Fee (per Section 29) £

Fees applied for,

Special Damage or Repair Fee (if any) (per Sec. 29) £

19

Travelling Expenses (if chargeable) £

Received by me,

Second Surveyor's Fee (if any) £

19

Surveyor to Lloyd's Register of Shipping

Committee's Minutes

TUE. 4 JAN 1938

Character Assigned
W.D. - Engin MaruWithdraw Class +
insert ()

General Committee

Thursday, 6 January, 1938

Classing Committee

Decision confirmed

© 2021

Lloyd's Register
Foundation

W1312-0212