

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 19... When handed in at Local Office 19... Port of LondonDECLASSIFIED
BOX No. 164No. in Survey held at Reg. Boat 15095 6645 on the Wood Iron Steel K. "Swan II" Date, First Survey (No. of Visits) Last Survey YEAR. MONTH. 1902 11By whom Cook, Welton & Gemmell When 1902 11Tonnage: GROSS 239 Built at Shull Owners' Address The Hewitt Fishing Co. Ltd. (if not already recorded in Appendix to Register Book).UNDER DK. 216 Owners R. S. Hewitt Port belonging to LondonNET 96 Managers R. S. Hewitt Destined Voyage

Surveyed Afloat or in Dry Dock? Name of Dock Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

WB=CellDBorDBa feet; uE&B feet; f feet feet total capacity tons. FPT tons; APT tons; MT feet tons.

N.B.—All alterations in the existing records should be underlined. If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 107767 Port W

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

SUMMARY OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Fair'd or Repaired								
Fair'd or Repaired in place								

PRESENT CONDITION OF THE	State if Tanks have been examined inside	Air and Sounding Pipes	Copper, or Y.M. of Wood Vessels (state if on Felt). When put on, Month Year
Decks	State if Tanks now tested	Dblng. Plates under Sounding Pipes	Boats
Caulking of Decks	Bulkheads	Engine Room Skylights	Masts, Yards, &c.
Coamings	Ceiling	Coal Bunkers, Open'gs, Lids, &c.	Condition, how ascertained (State if wedges removed)
Beams & Fastenings	Cement or Asphalt (State which.)	Oil Bunkers	Sails
Outside Plating	Rudder	Scuppers	Equipment letter
" " in way of sidelights	Steering gear and its connections	Cargo Hatchways	Anchors, No. of
Breasthooks	Windlass	Hatches	Chain Locker
Transoms	Have pumps now been examined and found efficient?	Planking of Wood Vessels	Cables (State if now ranged)
Frames	Have Sluice Valves now been examined and found efficient?	Caulking ditto	" length (on board) mean diam.
Reverse Frames	Have Watertight Doors now been examined and found efficient?	Treenails ditto	" Rule length size
Longitudinals	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stemson ditto	Hawser & Warps
Transverses		Transoms Pointers, & Crutches ditto	Standing and Running Rigging
Floors		Timbers of Frame at openings ditto	
Keelsons		Ditto Ditto at other places ditto	
Stringers		Stringers, Clamps & Shells ditto	
Inner Bottom Plating		Salting ditto (State if examined.)	

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:— "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,24," or "to remain as classed and to have record of survey, 1,24, and the notations of ss No. 1-24 and ptND24, &c."

Survey Fee (per Section 29)	£	Fees applied for, 19
Special Damage or Repair Fee (if any) (per Sec. 29)	£	Received by me, 19
Travelling Expenses (if chargeable)	£	
Second Surveyor's Fee (if any)	£	

Committee's Minute TUE 29 JUN 1937

Character Assigned Write Over

General Committee Thursday, 10 July 1937 Decision of Classing Committee confirmed

© 2021

Lloyd's Register Foundation