

Received by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

10 MAR 1933

VESSEL'S NAME Steel Tw. Sc. "MOCAMBIQUE" / Rpt. Lis. No. 2243,

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92).

Nature of Survey _____

The class is subject to hatch webs being fitted to No.2 hatch on upper deck.

The Lisbon Surveyor now reports the vessel placed in dry dock and the bottom cleaned and coated.

Hatch webs have now been fitted to No.2 hatchway on upper deck.

It is submitted the vessel appears worthy to remain as classed with record of survey 3,33 without special condition.

100A1)
with freeboard) without &c.
3,33 Lis)



© 2021

Lloyd's Register
Foundation

W1319-0090