

Undertaking Case

22 JUN 1933

Chief Surveyors 21. 6. 33.

Received from Chief Surveyors

EL'S NAME See T. S. Southland

Report Ddu. No. 1550.

For the CHIEF SHIP SURVEYOR ~~CHIEF ENGINEER SURVEYOR~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement." - (Extract from Sub-Committee's Report, 24/5/02.)

No. Mod. O.E. SURVEY PARTLY HELD.

due 5.29 When proposed to be completed

in of Survey held, &c.

Special Survey No. 1 due 5.31.

? General Examination

The S.S.No.1 became due 5.31, and no part of this survey has been held. The vessel has been laid up at Bluff, N.Z. since 1930, and the usual undertaking has been furnished.

The Dunedin Surveyor reports the vessel still laid up indefinitely.

In view of the fact that ^{1/2}a year has now elapsed since the year of grace expired, it is a matter for consideration whether a general examination should not be required to be held.

21.6.33

W. J. H. 2 MS



© 2021

Lloyd's Register
Foundation