

REPORT of SURVEY for REPAIRS, &c.

20 DEC 1937

Date of writing Report... When handed in at Local Office... Port of London
No. in Reg. Book. 34960 Survey held at Wood, Iron or Steel Tensan Mara
Date, First Survey... Last Survey... 19...
(No. of Visits)

TONNAGE:—
GROSS 2776 Built at Tama Skyd By whom Mitsui Bussan Kaisha when 1929 85
UNDER DK. 2398 Owners Laurel Kien K.K. Owners' Address
NET 1588 Managers Laurel Port belonging to Laurel
(if not already recorded in Appendix to Register Book).

Surveyed Afloat or in Dry Dock? WB=CellDBorDBa Name of Dock Laurel Destined Voyage Laurel
feet; uE&B feet; f feet
total capacity tons. FPT tons; APT tons; MT feet tons.
N.B.—All alterations in the existing records should be underlined.

Last Report, No. 10008 Port Kob

(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules and items remaining to complete the Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

CHARACTER.
For Special Survey.
Date of last Survey and of Periodical Surveys.
Years Assigned new survey.
Machinery and Boiler Surveys (including date of N.B. in any).
1100A1
3.37
SS Kob No 1-33
CL 3.37
DBS 3.37
OIL ENG.
Large batteries not fitted.

Society's Freeboard (if assigned) as painted on Ship and now verified ft ins.

Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

OIL ENGINE
CONTINUOUS SURVEY.

SUMMARY OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Fair'd or Repaired								
Fair'd or Repaired in place								

PRESENT CONDITION OF THE

Decks	State if Tanks have been examined inside	Air and Sounding Pipes	Copper, or Y.M. of Wood Vessels (State if on Felt.)
Caulking of Decks	State if Tanks now tested	Dblng. Plates under Sounding Pipes	When put on, Month Year
Coamings	Bulkheads	Engine Room Skylights	Boats
Beams & Fastenings	Ceiling	Coal Bunkers, Open'gs, Lids, &c.	Masts, Yards, &c.
Outside Plating	Cement or Asphalt (State which.)	Oil Bunkers	Condition, how ascertained (State if wedges removed)
" in way of sidelights	Rudder	Scuppers	Sails
Breasthooks	Steering gear and its connections	Cargo Hatchways	Equipment letter
Transoms	Windlass	Hatches	Anchors, No. of
Frames	Have pumps now been examined and found efficient?	Planking of Wood Vessels	Chain Locker
Reverse Frames	Have Sluice Valves now been examined and found efficient?	Caulking ditto	Cables (State if now ranged)
Longitudinals	Have Watertight Doors now been examined and found efficient?	Treenails ditto	" length mean diamr. (on board)
Transverses	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stemson ditto	" Rule length size
Floors		Transoms Pointers, & Crutches ditto	Hawser & Warps
Keelsons		Timbers of Frame at openings ditto	Standing and Running Rigging
Stringers		Ditto Ditto at other places ditto	
Inner Bottom Plating		Stringers, Clamps & Shells ditto	
		Salting ditto (State if examined.)	

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,24," or "to remain as classed and to have record of survey, 1,24, and the notations of ss No. 1-24.

Survey Fee (per Section 29)	£	Fees applied for,
Special Damage or Repair Fee (if any) (per Sec. 29)	£	19
Travelling Expenses (if chargeable)	£	Received by me,
Second Surveyor's Fee (if any)	£	19

Committee's Minute/

TUE. 4 JAN 1938

Character Assigned
WA
See
Superior Mara

Withdraw class &
insert (

Surveyor to Lloyd's Register of Shipping.
General Committee
Thursday, 6th January 1938
Classing Committee
decision confirmed
W1320-0260