

No 159

Lloyd's Register of Shipping,

(MEIKAI BUILDING)

32, AKASHI-MACHI,

KOBE, 26th January, 1929.

Cert. No. 1778.

This is to Certify that at the request

of Messrs. The Kobe Steel Works, Ltd, Kobe.

the Open Hearth Steel Forgings or Castings named below ~~was~~ ^{were} examined and tested at their works on December 22nd, 1928 to January 25, 1929 (5 visits)

and found to be as far as could be ascertained, sound and free from defect.

One (1) Propeller shaft 10-5/8" inches dia under sleeve fitted with a continuous liner in one piece.

~~Drop tests~~ Examined in finished condition.

Test Mark	Tenacity Tons/sq in	Elongation % in 2"	1" x 3/8" x 180° Band
C-2589-A-2	34.1	32	Good

This shaft is intended for Mitsui Bussan Kaisha,

Tam. Yard Ship No. 159 and ~~has~~ ^{have} been stamped as follows:-


C-2589-A-2
LLOYD'S
No. 1778
25-1-29
L.R.A.W.

Fee Yen 55.00
Expenses ,, 2.00

A Watt

Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:--
"While the Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society or for any error of judgment, default, or negligence of the Surveyors, other Officers or Agents of the Society."



Lloyd's Register
Foundation

W1320-0270