

REPORT of SURVEY for REPAIRS, &c.

Date of Survey Report... When handed in at Local Office... Port of London No. 176

No. in Reg. Book. 35575 Survey held at on the Wood, Iron or Steel Date, First Survey S.S. "TUNG LUNG" Last Survey 19

TONNAGE:- Built at Chicago By whom Chicago S.B. Co. When 1914-9
GROSS 1843 Owners Tung lung S.S. Co. Owners' Address (if not already recorded in Appendix to Register Book)
NET DEK. 1650 Managers Towa Kisen K.K. Port belonging to Yantai (China)
NET TONNAGE 1081

Surveyed, Afloat or in Dry Dock? Name of Dock Destined Voyage
Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

B=C, uE&B, f...
N.B.—All alterations in the existing records should be underlined.
If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

CHARACTER...
Date of last Survey and of Periodical Surveys.
Machinery and Boiler surveys (including date of N.B., if any).
DA 100A1
3-34
LMC 3-34
CL 3-34

Previous Report, No. 10006 Port Kobe

Medical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the nature and extent of Examinations and subsequent repairs. Repairs account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the placement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

S.S. NYK. No. 3-8-29.
S.S. Dal. No. 1-35
Cargo battens not fitted.

Where the Surveyor has not made a special damage report he is required to state whether he has rendered his services for this purpose and to whom and why they were declined

Society's Freeboard (if assigned) as painted on Ship and now verified ft. ins.

Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

CATEGORY OF DAMAGE REPAIRS :-	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items :-
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

PRESENT CONDITION OF THE	State if Tanks have been examined inside	Air and Sounding Pipes	Copper, or Y.M. of Wood Vessels (State if on Felt). When put on, Month Year
Condition of Decks	State if Tanks now tested	Dblng. Plates under Sounding Pipes	When put on, Month Year
Condition of Bulkheads	Bulkheads	Engine Room Skylights	Boats
Condition of Ceilings	Ceiling	Coal Bunkers, Open'gs, Lids, &c.	Masts, Yards, &c.
Condition of Plating	Cement or Asphalt (State which.)	Oil Bunkers	Condition, how ascertained (State if wedges removed)
Condition of Rudder	Rudder	Scuppers	Sails
Condition of Steering gear and its connections	Steering gear and its connections	Cargo Hatchways	Equipment letter
Condition of Windlass	Windlass	Hatches	Anchors, No. of
Condition of Pumps	Have pumps now been examined and found efficient?	Planking of Wood Vessels	Chain Locker
Condition of Sluice Valves	Have Sluice Valves now been examined and found efficient?	Caulking ditto	Cables (State if now ranged)
Condition of Watertight Doors	Have Watertight Doors now been examined and found efficient?	Treenails ditto	length (on board) mean diam.
Condition of Ventilators and their Coamings	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stemson ditto	Rule length size
Condition of Bottom Plating	Have Ventilators and their Coamings been examined and found efficient?	Transoms Pointers, & Crutches ditto	Hawser & Warps
		Timbers of Frame at openings ditto	Standing and Running Rigging
		Ditto Ditto at other places ditto	
		Stringers, Clamps & Shelves ditto	
		Salting (State if examined.) ditto	

General Observations, Opinion as to Class, Recommendation, &c. :-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,24," or "to remain as classed and to have record of survey, 1,24, and the notations of ss No. 1-24 and ptND24, &c."

Survey Fee (per Section 20)	£	Fees applied for	19
Special Damage or Repair Fee (if any) (per Sec. 20)	£	Received by me	19
Travelling Expenses (if chargeable)	£		
Second Surveyor's Fee (if any)	£		

Committee's Minute
Character Assigned
Withdrawn class
FRI 1 APR 1938
Must new own
Kob (Copy)
Sunset

Surveyor to Lloyd's Register of Shipping.
Special General Committee
Thursday, 7th April, 1938
Lloyd's Register of Shipping
Decision of Classing
Committee confirmed

92176

W1321-0086

Is Certificate required? If so, to be sent to

Posted
10/3/38