

2m.11.36.

1

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME

"OSWALDIAN"

Report

Lon.

No. 10364

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

When due

The 2nd S.S.No.2 became due 7,38.

The Owners recently wrote intimating their decision to withdraw the class of this trawler from the Register Book.

It is submitted the vessel's class be withdrawn from the Register Book and Three Dots (...) inserted in lieu thereof, indicating withdrawal of class at Owners' request.

Withdraw Class

Insert (...)

*[Signature]*  
5.10.38



© 2021

Lloyd's Register  
Foundation

W1324- 0209

Fees applied for,