

(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules and items remaining to complete the Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and

7.36  
6.31  
35

2500,10.38.

ent to Chief Surveyors

Received from Chief Surveyors 24 JAN 1939

ESSEL'S NAME "DOCTOR LEE" Report Lon. No. 103735

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

When due

The class is subject to the bunker bulkhead being permanently repaired, and the vessel being laid up action was deferred.

*A Special Survey No 2 will become due 6.39*


In reply to enquiry the Owners now write that they are "not keeping this vessel in class".

It is submitted the class of this vessel be withdrawn from the Register Book and Three Dots (...) inserted in lieu thereof, indicating withdrawal of class at Owners' request.

Withdraw Class

Insert (...)

PLATING to be DRILLED when vessel is 24 years old, or at next Special Survey thereafter.



© 2021

Lloyd's Register Foundation

W1325-0100

*h.f.*  
23.1.39