

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 19... When handed in at Local Office 19... Port of Kobe LONDON

No. in Reg. Book 8544 Survey held at on the Wood, Iron or Steel Date, First Survey "TYOZO MARU" Last Survey 19... (No. of Visits)

DISCLOSED
BY No. 194
YEAR 1927-3

TONNAGE— Built at Nagasaki By whom Mitsubishi Zosen Kaisha, Ltd. Owners Osaka Syosen K.K. Managers - Port belonging to Osaka
GROSS 2611
UNDER DE. 1898
NET 1373

Surveyed Afloat or in Dry Dock? WB=CellDBorDBa Name of Dock Kobe Destined Voyage M-Japan
feet; uE&B feet; f feet
total capacity tons. FPT tons; APT tons; MT feet tons.
N.B.—All alterations in the existing records should be underlined.

Last Report, No. 10557 Port Kobe

CHARACTER	Particulars of Classification
+ 100 A1	+ LMCS 2, 38
2, 38	2, 38
51 Osa 16.3 - 2, 38	DBS 2, 38
	CL 2, 36
Oil Engine	

(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules and items remaining to complete the Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined. Society's Freeboard (if assigned) as painted on Ship and now verified

Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

REPAIRS, OR EXAMINATION AS PER RULE, FOR

SUMMARY OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Fair'd or Repaired								
Fair'd or Repaired in place								

PRESENT CONDITION OF THE	State if Tanks have been examined inside	Air and Sounding Pipes	Copper, or Y.M. of Wood Vessels
Decks	State if Tanks now tested	Dblng. Plates under Sounding Pipes	(State if on Fall.) When put on, Month Year
Caulking of Decks	Bulkheads	Engine Room Skylights	Boats
Coamings	Ceiling	Coal Bunkers, Open'gs, Lids, &c.	Masts, Yards, &c.
Beams & Fastenings	Cement or Asphalt (State which.)	Oil Bunkers	Condition, how ascertained (State if wedges removed)
Outside Plating	Rudder	Scuppers	Sails
" " in way of sidelights	Steering gear and its connections	Cargo Hatchways	Equipment letter
Breasthooks	Windlass	Hatches	Anchors, No. of
Transoms	Have pumps now been examined and found efficient?	Planking of Wood Vessels	Chain Locker
Frames	Have Sluice Valves now been examined and found efficient?	Caulking ditto	Cables (State if now ranged)
Reverse Frames	Have Watertight Doors now been examined and found efficient?	Treenails ditto	" length mean diam. (on board)
Longitudinals	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stemson ditto	" Rule length size
Transverses		Transoms Pointers, & Crutches ditto	Hawser & Warps
Floors		Timbers of Frame at openings ditto	Standing and Running Rigging
Keelsons		Ditto Ditto at other places ditto	
Stringers		Stringers, Clamps & Shelves ditto	
Inner Bottom Plating		Salting ditto (State if examined.)	

General Observations, Opinion as to Class, Recommendation, &c.:— State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1, 2, 4," or "to remain as classed and to have record of survey, 1, 2, 4, and the notations of ss No. 1-24."

Survey Fee (per Section 20)	£	Fees applied for,	19
Special Damage or Repair Fee (if any) (per Sec. 20)	£	Received by me,	19
Travelling Expenses (if chargeable)	£		
Second Surveyor's Fee (if any)	£		

Committee's Minute FRI 27 JAN 1939
Character Assigned M. Andran class
Surveyor to Lloyd's Register of Shipping.
General Committee
Thursday 2nd February 1939
Decision of Classing Committee confirmed

The Surveyors are requested to contribute on or before the space for Committee's Minutes.

W1329-0053

If so, to be sent to