

COPY.

# Lloyd's Register of Shipping.



Port NEW YORK

SEPTEMBER 2, 1941.

**This is to Certify** *that I have*

*Surveyed the Boilers and Machinery of the S.S. "UNIWALCO" 9755  
tons gross register of Durban for part Machinery Survey, Boiler  
Survey, examination of Tailshaft, and repairs*

*and that I have transmitted to the Committee of Lloyd's  
Register of Shipping, London, a Report stating that all  
recommendations made by me in connection therewith have  
been carried out to my satisfaction, and that I have*

**Recommended** *that the record of 4LMC,MS (with date) when the  
survey is completed, B.S. 8,41, and T.S. (CL) 7,41, subject to  
Pr. Ba. not being used.*

*be made in the Register Book in the case of this vessel.*

**As Part M.S.-** Examined all main engine, crank, thrust, and inter-  
mediate shafting and bearings. H.P.Cylinder piston and slide valve  
1st M.P.Cylinder piston and rod, 2nd M.P.Cylinder piston and slide  
valve. Main condenser examined and water tested. Main engine driver  
air pump and main circulating pump throughout including for'd. and  
aft engines.

(Signed) C. R. Maplestone

Engineer Surveyor to Lloyd's Register.

**To Complete M.S.-** 1st M.P. slide valve and L.P.Cylinders piston and  
slide valve. All main engine attached pumps except the air pump. All  
auxiliary pumps except the main circulator. Electric installation and  
pumping arrangements. Windlass and steering engine to be examined.

This Certificate is issued upon the terms of the Rules and Regulations of the Society which provide that  
"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly  
executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances  
whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in  
any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of  
any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

Cert. B1.)



Lloyd's Register  
Foundation

W133-0069