

# REPORT of SURVEY for REPAIRS, &c.

19 AUG 1938

Date of writing Report ..... 19... When handed in at Local Office ..... 19... Port of London  
No. in Reg. Book. 86562 Survey held at on the Wood, Iron or Steel Date, First Survey YAKUMO MARU Last Survey 19

TONNAGE - Built at Tokyo By whom Ishikawajima S.B. & E. G. Ltd YEAR 1919  
GROSS 3198 Owners Osaka Suisen K.K. Owners' Address G. Ltd  
UNDER DK. 2676 Managers Osaka Port belonging to Osaka  
NET 1913

Surveyed Afloat or in Dry Dock? WB=CellDBorDBa Name of Dock Kob Destined Voyage Osaka  
feet; uE&B feet; f feet  
total capacity tons. FPT tons; APT tons; MT feet tons.  
N.B. - All alterations in the existing records should be underlined.

Last Report, No. 10511 Port Kob

(Periodical surveys, when held, must be reported in detail and seriatim in the terms of the Rules and items remaining to complete the surveys should be summarised. State clearly the cause of repairs, if any, and, in detail, the nature and extent of examinations and subsequent repairs. Repairs on account of damage (the cause of which must be stated) should be separated from repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

CHARACTER, for Special Survey, Date of last Survey and of Periodical Surveys.	Years Assigned or expired.	Machinery and Boiler Surveys (including date of N.B., in any).
+ 100 A1	1, 38	+ LMC 1, 38
ss Osa No 3 - 10, 31		CL 1, 38
ss Kob No 1 - 35		

Society's Freeboard (if assigned) as painted on Ship and now verified } ft. int.

Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

8 - Japan  
8.356...  
F

SUMMARY OF DAMAGE REPAIRS :-	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items :-
Renewed								
Removed and Paired or Repaired								
Faired or Repaired in place								

PRESENT CONDITION OF THE	
Decks	State if Tanks have been examined inside
Caulking of Decks	State if Tanks now tested
Coamings	Bulkheads
Beams & Fastenings	Ceiling
Outside Plating	Cement or Asphalt (state which.)
" " in way of sidelights	Rudder
Breasthooks	Steering gear and its connections
Transoms	Windlass
Frames	Have pumps now been examined and found efficient?
Reverse Frames	Have Sluice Valves now been examined and found efficient?
Longitudinals	Have Watertight Doors now been examined and found efficient?
Transverses	Have Ventilators and their Coamings been examined and found efficient?
Floors	
Keelsons	
Stringers	
Inner Bottom Plating	
Air and Sounding Pipes	
Dbing. Plates under Sounding Pipes	
Engine Room Skylights	
Coal Bunkers, Open'gs, Lids, &c.	
Oil Bunkers	
Scuppers	
Cargo Hatchways	
Hatches	
Planking of Wood Vessels	
Caulking ditto	
Treenails ditto	
Breasthooks & Stems ditto	
Transoms Pointers, & Crutches ditto	
Timbers of Frame at openings ditto	
Ditto Ditto at other places ditto	
Stringers, Clamps & Shells ditto	
Salting ditto (state if examined.)	
Copper, or Y.M. of Wood Vessels (state if on Roll.) When put on, Month Year	
Boats	
Masts, Yards, &c.	
Condition, how ascertained (state if wedges removed)	
Sails	
Equipment letter	
Anchors, No. of	
Chain Locker	
Cables (state if now rigged)	
" length (on board) near diamr.	
" Rule length size	
Hawser & Warps	
Standing and Running Rigging	

### General Observations, Opinion as to Class, Recommendation, &c. :-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example: "to remain as now classed in the Register Book without fresh record of Survey;" "to remain as classed and to have record of survey, 1,24," or "to remain as classed and to have record of survey, 1,24, and the notations of ss No. 1-24.

Survey Fee (per Section 20)	£	Fees applied for,
Special Damage or Repair Fee (if any) (per Sec. 20)	£	19
Travelling Expenses (if chargeable)	£	Received by me,
Second Surveyor's Fee (if any)	£	19

Surveyor to Lloyd's Register of Shipping.

Committee's Minute/

Character Assigned  
Work Only  
Kob  
Coast

8 AUG 1938  
Withdraw Class and  
mark  
all

General Committee  
Thursday, 1<sup>st</sup> September 1938  
Classing Committee's decision confirmed  
Foundation

W1330-0101

Is Certificate required? If so, to be sent to