

2500,10,38.

Received from Chief Surveyors

13 JAN 1939

Sent to Chief Surveyors

VESSEL'S NAME

"Kuvera"

Report

Lon.

No.

103700

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

When due

The class is subject to stem and indented plating being repaired at the Owners' convenience.

The Boiler Survey became due 11,38.

The Aberdeen Surveyors now write enclosing a letter from the Owners intimating their decision to withdraw this vessel from class.

It is submitted the vessel's class be withdrawn from the Register Book and Three Dots (...) inserted in lieu thereof, indicating withdrawal of class at Owners' request.

Withdraw class

Insert (...)

11.1.39

W1331- 0168



© 2021

Lloyd's Register
Foundation