

For the information of Surveyors and the Committee only.

Received at ..... Office ..... 19

# Lloyd's Register of Shipping.

(Report on Vessel No. .... Port .....) )

## To. .... SHIP FORGINGS OR CASTINGS.

I have to report that the undermentioned ~~Iron or Steel Forgings or~~  
Castings, manufactured by Columbia Steel Company,  
Pittsburg, California for the Vessel No. 15, being built  
by J. Coughlin & Sons of Vancouver, B. C.  
have been inspected by me as set forth below and found to be, so far as can  
be seen, sound.

Lower section stern frame

Forgings or Castings.

Lloyd's

672

2-20

Alv. Lawson

San Francisco.


Lower	STERN FRAME.	RUDDER FRAME.	STEM.
.....	<u>O. H. Steel</u>		
.....	<u>Cast</u>		
.....	<u>as per plan</u>		
.....	<u>rough</u>		
Inspection			
Inspected	<u>27-1-20 2-2-20.</u>		
INGS.			
Standard Cast			
ices.	<u>60800</u>		
are inch	<u>65800</u>		
cent. ...	<u>28</u>		
Test—	<u>29</u>		
fracture	<u>120</u>		
ground ...	<u>120</u>		
est—	<u>9'</u>		
ding to Rules			
satisfactory...	<u>Yes</u>		

DRAWINGS OF FRAMES SHOWING POSITION AND DESCRIPTION OF WELDS OF FORGINGS.

of any chargeable) \$ 15.00 :

be paid at San Francisco.

on, state whether scrap or puddled Iron. If of Steel, state whether made on the Open Hearth process.



© 2021

Lloyd's Register  
Foundation

W 1331-0228