

"SUSARION."

In a letter dated the 14th October 1938 the Owners requested that the classification of vessels belonging to their Fleet might be withdrawn as the vessels became due for survey.

In the case of this vessel the *Boiler Survey* became due at the end of 3.39. and it is submitted that the vessel's class be now withdrawn from the Society's Register Book and three dots (...) inserted in lieu thereof indicating withdrawal of class at Owners' request.

1938
12.4.39
[Signature]



© 2021

Lloyd's Register
Foundation

W1335-0051