

by Chief Ship Surveyor

Received from Chief Ship Surveyor

SHIP'S NAME Steel S.S. "CANADIAN IMPORTER" Rpt. Vancouver No. 782

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.


("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

of Survey First Entry.

The Superintendent at Lloyd's Proving House, Cardiff, should be requested to forward particulars of Chain Cable Certificate No. 21197, also of Anchor Certificates Nos. 13539, 13540, 13544 & 13547,

Dr. 30.3.20.

in Lb. 31.2.20



all

30-3-20

Lloyd's Register
Foundation

W1335-0092