

27 JUL 1938

"LOYAUTE".

The Screwshaft Survey became due in 7,37 and
the 2nd Special Survey No.1 in 11,37. *B.S. 1,38*

Action has been deferred from time to time
and on the 11th instant the Owners were informed by cable
that unless the Screwshaft Survey was held immediately
the vessel would lose her class.

In reply the Owners cabled that the vessel
would dry dock at Brisbane on the 20th instant.

The Brisbane Surveyor now cables that the Owners
do not desire to retain the class.

It is submitted the class be expunged with
a Red Line indicating that the Society's Rules have not
been complied with.

[Handwritten signatures]

© 2021 27.7.38.



W1336-0128
Lloyd's Register
Foundation

Transfer Ink. (M)
on or below the space
Lloyer