

Lt. Hermone

Howe No. 5755-8.

It is submitted that the Howe Surveyors  
be requested to state how far pressure  
the main safety valves have been adjusted  
whether they are fitted with easing gear.

Mr. Howe  
8/9/06

J.L.S.  
8.9.06

Howe  
8.9.06

© 2021

Lloyd's Register  
Foundation

W1337-0137

Build  
Galleries

Elliptical  
Clincher  
Rivets

Length at quarter of depth from top of weather deck at  
side amidships to bottom of keel  
Main breadth to outside of plank  
Depth in hold from tannage deck to ceiling at midships