

Chief Surveyors

Received from Chief Surveyors

EL'S NAME

"KIMIABAD"

Report

Lon.

No.

107564

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

of Survey

When due

A S.S.No.1 became due 8,38 and the shell
plating requires to be drilled at this Survey (vessel ^{over} 24 years old).

The tug has been laid up.

In reply to enquiry the Bombay ^{Surveyor} now forwards
a letter from the Owners intimating their decision to allow the
class to lapse.

It is submitted the class of this vessel might
be withdrawn from the Register Book and Three Dots (...) inserted
in lieu thereof, indicating withdrawal of class at Owners' request.

Withdraw class

Insert (...)

[Handwritten signature]
19.7.39 *[Handwritten signature]*



© 2021

Lloyd's Register
Foundation

W1343-0155