

Received by Chief Ship Surveyor 29.8.10

Received from Chief Ship Surveyor .....

VESSEL'S NAME Sheells. W.S. Porter

Rpt. S. F.

No 1490

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey DAMAGE.

Damage through ice

now repaired as follows:-

	Plates	Frames	R.Frames	Floors	Beams	Str.	Plates	Dk.	Plates
Renewed .....									
Removed and faired } or repaired.....	4	✓							
Faired or repaired } in place.....		6							

Other items:-

2 shakes of plating on each side doubled for about 12 feet from stem.

It is submitted the vessel is worthy to remain as classed with entire record of Survey as recommended

*AR*

29.8.10

© 2021



Lloyd's Register Foundation

W1351-0144