

# REPORT OF SURVEY FOR REPAIRS, &c.

Place of writing Report... 19... When handed in at Local Office... 19... Port of London

No. in Reg. Book. 36857 Survey held at on the Wood, Iron or Steel to Steamer "Yokohama Maru" Date, First Survey... Last Survey... 19

TONNAGE - GROSS 6143 Built at Nagasaki By whom Mitsui Bishi S.K. & Co. Ltd YEAR. MONTH. 1942 5  
OWNER DK. 5820 Owners Nippon Yusen K.K. Owners' Address (if not already recorded in Appendix to Register Book).  
NET 3790 Managers... Port belonging to Tokyo.

Surveyed Afloat or in Dry Dock? Name of Dock... Destined Voyage...  
ellDBorDBa feet; uE&B feet; f...  
tal capacity tons. FPT tons; APT tons; MT feet tons.

N.B.—All alterations in the existing records of tanks should be inserted.

ast Report, No. 6704 Port Yka

Periodical surveys, when held, must be reported in detail and seriatim in the terms of the Rules and items remaining to complete the surveys should be summarised. State clearly the cause of repairs, if any, and, in detail, the nature and extent of examinations and subsequent repairs. Repairs on account of damage (the cause of which must be stated) should be separated from repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars respecting this case.

damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

CHARACTER, for Special Survey Date of last Survey and of Periodical Surveys.	Machinery and Boiler Surveys (including date of N.B., if any).
<u>4100A1</u>	<u>TMC 7-37</u>
<u>Shelter dk. with</u>	<u>BS 6-39</u>
<u>freeboard</u>	<u>OG 6-39</u>
<u>6-39</u>	
<u>SS 106 2nd No. 3-7-37</u>	
<u>Banging cargo oil</u>	<u>F.P. above 150°F</u>
	<u>in deep tanks</u>

Society's Freeboard (if assigned) as painted on Ship and now verified } ft. ins.

Was a damage report made by anyone else? If so, by whom?

PAIRS, OR EXAMINATION AS PER RULE, FOR

SUMMARY OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items:
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

PRESENT CONDITION OF THE	Bulkheads	Engine Room Skylights	Copper, or T.M. (State if on Felt.)
Planking of Decks	Ceiling	Coal Bunkers, Openings, Covers, &c.	When fitted, Month Year
Stowings	Cement or Asphalt	Oil Bunkers	Boats
Rims & Fastenings	Rudder	Scuppers	Masts, Yards, &c.
Outside Plating	Steering gear and its connections	Cargo Hatchways	Condition, how ascertained (State if wedges remain)
" " in way of sidelights	Windlass	Hatches	Equipment letter
Frames	Have pumps been examined and found efficient?	Planking	Anchors, No. of
Inverse Frames	Have Sluice Valves been examined and found efficient?	Caulking	Cables (State if now rigged)
Longitudinals	Have Watertight Doors been examined and found efficient?	Treenails	" length mean diam. (on board)
Transverses	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stemson	" Rule length size
Decks	Air and Sounding Pipes	Transoms, Pointers & Crutches	Chain Locker
Beams	Doubling Plates under Sounding Pipes	Timbers of Frame at openings	Hawsers & Wamps
Stringers		" " at other places	Standing and Running Rigging
Inner Bottom Plating		Stringers, Clamps & Shelves	Sails
Have the Tanks been examined internally?		Salting (State if examined.)	
Have the Tanks been tested?			

### General Observations, Opinion as to Class, Recommendation, &c.:

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example, "to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."


Survey Fee (per Section 29)	£	Fees applied for,	19
Special Damage or Repair Fee (if any) (per Sec. 29)	£	Received by me,	19
Travelling Expenses (if chargeable)	£		
Second Surveyor's Fee (if any)	£		

10th, 438.—Transfer The Surveyors are requested not to...

Committee's Minute  
Character Assigned Withdraw class insert  
Wrote On Kob (C.P.)

FRI. 5 APR 1940

Surveyor to Lloyd's Register of Shipping.  
Confirmed by General Committee  
Thursday 11 April 1940



W1354-0005