

offered his services for this purpose and to whom and why they were declined ✓

Society's Freeboard  
painted on Ship and

AF

"URSULA RICKMERS"

On Tuesday, 4th June, 1940, a list of German Owned vessels, classed with Lloyd's Register, was submitted to the Classing Committee, who gave instructions that the class of each vessel should be omitted from the Reprint of the Register Book for 1940-41.

(Original papers with "H" Department).

The list referred to above included the name of the S.S. "URSULA RICKMERS".

For Mr. Boxall )  
H Dept. )  
Mr. Munro ) tp note.

DB 218

© 20203  
Section



Lloyd's Register  
Foundation

W1359 - 0142

Longitudinals	✓	Have Sluice Valves now been examined and found	✓	Breasthooks & Stemson ditto	✓
	✓		✓	Transoms Pointers & Crutches ditto	✓

whom

ch

ch

ch

Items :

Copp

W

Boat

Mast

Cond

(S

Sails

Equi

Anch

Chai

Cabl