

W136-0007

Surveyors \_\_\_\_\_

Received from Chief Surveyors \_\_\_\_\_

NAME Stl Ss "PULPIT POINT" Report Link No. 18616**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

Cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/93.)

Survey 1st Entry When due Revised Rules

✱ 100A.1. (Steel). Carrying Petroleum in Bulk  
 2 D<sup>ns</sup> (Stl). Web frames, longitudinal framing.  
 Cell DB, E. B 65' f 35' 318t, F.P.T. 190t, A.P.T. 130t.  
 F.K, 18 B.H, pt cm, Lloyds A. CP.  
 P 118', B 43', F 42'. machy ap



© 2021

Lloyd's Register  
Foundation

28.10.20

5/11/26  
 The Surveyor should be requested ~~to~~ <sup>to reforward</sup> forward the forging reports.