

"EUROFELD."

M/M 1360
27 JUN 1939

1

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME

EUROFELD

Rpt.

Rot.

No.

28267

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

DAMAGE.

Damage through

Collision

now repaired as follows:-

	Shell Plates	Main Frames	R Frames	Floors & Bracket Floors	Inner Bottom Plates	Deck Plates	Beams
Renewed	19						
Removed and faired or repaired.....	1	2					
Faired or repaired in place.....	2	2				5	

Other items:-

Vessel placed in dry dock
minor repairs effected.

It is submitted the vessel is worthy to remain as classed with
record of Survey 6.39

100 A1
Shelter dk. with Fld.
6.39 Rot.
Carrying Pet. in Bulk.
Fitted for oil fuel etc.



26.6.39

© 2020

Lloyd's Register
Foundation

W1360-0008