

CHARLES D. HOLMES & CO. LTD

ENGINEERS,
BOILER MAKERS,
IRON & BRASS FOUNDERS,
GENERAL SHIP REPAIRERS,
ELECTRIC WELDERS & METAL SPRAYERS.

HULL ENGINEERING WORKS




TELEPHONES:
HEAD OFFICE 16053 (3 LINES)
PRINCE'S DOCK 35528.
WELDING WORKS 15249.

TELEGRAMS:
"COMPOUND, HULL"

HULL 22nd March 19 39

Messrs. Lloyd's Register of Shipping,
71, Fenchurch Street,
LONDON, E.C.3.



Dear Sirs,

With regard to the deformation which has taken place in the furnaces of the boilers of the Steam Trawlers "Kingston Chrysolite" and "Kingston Ceylonite" owned by The Kingston Steam Trawling Co., Ltd., of which we understand you have had full particulars from your Hull Office, and which you are at present investigating, we should like your report at your earliest convenience as this is a matter of great urgency to the Owners.

These boilers were built to your Survey and Class, and we desire your opinion as to whether the occurrence is any detriment to Classification now or in the future.

We are arranging with Mr. Little, of Messrs.



© 2020

Lloyd's Register
Foundation

W1360 - 0095 1/2

Messrs. Lloyd's Register of Shipping

22/3/39

T. R. Little & Co., of Liverpool, to survey one of the boilers at an early date, and shall be glad to know if you would wish one of your Principal Surveyors to attend at the same time. We think it advisable for all parties to examine and discuss the furnaces at the same time.

An early reply will oblige.

Yours faithfully,

P. PRO CHARLES D. HOLMES & CO., LTD.

Harold Shearson DIRECTOR.




© 2020

Lloyd's Register
Foundation

0095 2/2

Referred to the Chief Engineer Surveys



23 MAR 1939

Also for Mr. Hill to note.



© 2020

Lloyd's Register
Foundation