

1

sent to Chief Surveyors

5 5 13

Received from Chief Surveyors

65

VESSEL'S NAME

SS Agnes Ellen

Report

flc

No.

31987

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement.)—Extract from Sub-Committee's Report, 24/5/02.)

Nature of Survey

ss No. 1 When due 12 12 etc
Screw shaft due 12 10

The class of this vessel is subject to some repairs to the forecastle side plating and frames being effected when the 1st s.s. No. 1 which became due in December last is held.

The Liverpool Surveyors now forward a letter which they have received from the Owners in which it is stated that they have decided not to continue the vessel's class in the Society's Register.

It is submitted the vessel's class be omitted from the ensuing re-print of the Register Book.

E. G. G. *M.* *R. B. M.*
5. 5. 13
Pub.
6. 5. 13

Class omitted from
New Book A.K.A. 45713



© 2021

Lloyd's Register
Foundation

W1363-0089