

COPY.

PORT OF GLASGOW

29th. October, 1912.

Dear Sirs,

With reference to the survey which has recently been held at Bowling on your steamer "AGNES ELLEN", I beg to acquaint you that the Committee have had before them at their meeting to-day the Surveyor's report from which it appears that the fore-castle side plating and 2 frames in way of same on starboard side were found indented and a number of rivets broken and seams started, and that the defective rivets have been cut out and new bolts and grumets fitted and the seams recaulked.

It is understood to be your intention to have the indented plating, frames and rivets permanently dealt with when the vessel is submitted to the Special Survey No.1 which will become due at the end of the present year and the Committee have accordingly continued the vessel as classed subject to this being done.

I am, Dear Sirs,

Yours faithfully,

Secretary to the
Glasgow Committee.

Messrs. J.J. Monks (Preston) Lim.,
8a, Rutherford Place,

© 2021

Lloyd's Register
Foundation

W1363-0101