



Lloyd's Register of Shipping,

2, Laidlaw Building,
Battery Road,

LLOYD'S REGISTER,
LONDON.

REC'D - 9 JAN 1923

Singapore, 7th, December, 1922

ANSW

W. H. FRASER,
ROYAL NAUTICAL AND ENGINEER SURVEYOR.

ference

Dear Sir,

I beg to confirm my cable sent to you today regarding
the "Anamba's shell plate drillings reading:

"Anamba "L"strake to "F" strake starboard side amidships
10/20,7/20,10/20,8/20,10/20,8/20, portside amidships 10/20,
9/20,9/20,7/20,10/20,9/20, Starboard side forward 7/20,7/20,
10/20,7/20,7/20,8/20, portside forward 7/20,7/20,10/20,
7/20,7/20,8/20, starboard side aft 7/20,7/20,10/20,7/20,
8/20,8/20, portside aft 8/20,7/20,10/20,7/20,8/20,9/20."

I am, Dear Sir

Your Obedient Servant

W. H. Fraser

The Secretary

LONDON



© 2021

Lloyd's Register
Foundation

W1365-0161

