



Lloyd's Register of Shipping,

LLOYD'S REGISTER,
LONDON.

2, Laidlaw Building,
Battery Road,

REC'D - 8 JAN 1923

Singapore, 13th, December, 1922

ANSW _____

H. FRASER,
ENGINEER SURVEYOR.

Dear Sir,

I beg to acknowledge receipt today of your cable of the 11th instant regarding the shell plate thicknesses of the S.S. "Anamba" reading:-

"Anamba plating approved provided all plates below 8/20" must be doubled or renewed in first strake below main deck sheer strake within half length amidships."

The above mentioned plating will have attention.

I would add that the cable was inadvertently addressed to "Register" Singapore instead of the registered telegraphic address "Surveyor".

I am, Dear Sir

Your Obedient Servant

H. Fraser

The Secretary

LONDON



© 2021

Lloyd's Register
Foundation

w 1365-0162

Referred to Mr. S. A. Hill.

Referred to Mr. S. A. Hill.

CS-2

-8 JAN 1923

LONDON

The secretary

Woodstock

YOUR OBLIGED SERVANT

I am, Dear Sir,

reference "Sulphur" of the registered telegraph
"Register" Singapore dated 7th Dec 1922 addressed to
I would say the cable was immediately addressed to
The above mentioned business will have attention.

order when book order with their order
order when book order with their order
order when book order with their order

Yours faithfully,
S. A. Hill

and with that regard the above state the business of the
I beg to acknowledge receipt of your cable of

Dear Sir,

© 2021 Lloyd's Register Foundation

Singapore, 13th, December, 1922

Battery Road,
s, Leaden Wall Building

Registered in Singapore
Lloyd's Register

REGD
- 8 JAN 1923
LONDON

