



Lloyd's Register of Shipping.

LLOYD'S REGISTER,
LONDON.

2, Laidlaw Building,
Battery Road,

REC'D - 1 JAN 1923

Singapore, 6th, December, 1922

V. H. FRASER,
ENGINEER SURVEYOR.

ANS'D

Dear Sir,

I beg to confirm my cable of the 4th instant reading:-

"Anamba owners desire vessel to be re-classed
forward particulars of original thicknesses
of plating decks floors."

& to acknowledge receipt of your cable of the 5th instant in
reply reading:-

"Anamba to entitle vessel to re-classification
S.S.2nd No.3 must be completely held, all
necessary repairs carried out & all defects
made good to your satisfaction plating must be
drilled report results of drillings at once
equipment must be in accordance with Society's
Rules exercise greatest care to ensure
exhaustive survey."

I am, Dear Sir

Your Obedient Servant

The Secretary
LONDON



© 2021
V. H. Fraser.

Lloyd's Register
Foundation

W1365-6163

RECEIVED
M. H. FRASER
ENGINEER SURVEYOR

Receit