

COPY.

TRANSLATION OF CABLEGRAM SENT 5.12.22 TO THE
SOCIETY'S SURVEYOR AT SINGAPORE.

ANAMBA (Vessel's Name)

WIKXA - to entitle vessel to classification or reclassification
..... must be completely held, all necessary repairs
carried out and all defects made good to your
satisfaction.

WIDWU - 2nd and subsequent S.S.No.3

SNESH - plating must be drilled

SHYTA - report/ results of drillings at once

WQFIM - equipment

VIDUD - must be

VEVBI - in accordance with

VIVAP - Society's Rules

VENIC - exercise greatest care ensure exhaustive survey.



© 2021

Lloyd's Register
Foundation

W1365-0173