

are they fitted with easing gear ✓ In case of donkey boilers, state whether steam from main boilers can enter
Smallest distance between boilers or uptakes and bunkers or woodwork ✓
INSIDE
Main dia. of boilers 14'

COPY.

DISCLOSED
SECTION
5

Lloyd's Register of Shipping.

71, Fenchurch Street, E.C. 3.

ENCLOSURE

20th September, 1921.

Dear Sir,

Reverting to previous correspondence relative to the dredger "AGNES", I enclose herewith for your information a copy of Liverpool Report No. 82681 on the boilers which have been made for this vessel and shall be glad if you will give the case the necessary attention in due course.

You will be so good as to return the enclosed copy of report to this Office duly completed after the boilers have been fitted on board the vessel.

I am, Dear Sir,

Yours faithfully,

Secretary.

J. C. Morison, Esq.,

EAST LONDON,

South Africa.

W1367-0179



© 2021

Lloyd's Register
Foundation

Committee's Minute LIVERPOOL.

13 SEP 1921

Engineer Surveyor to Lloyd's