

Are the shell plates welded or flanged *no.* Description of riveting:

No. 5752

Made by

Riley Bros

mpv "Naensdrecht."

Mdb

Report No.

12992

a copy of

It is submitted that this Report be forwarded to  
the Rotterdam Surveyors for their guidance and  
for completion.

Date

4/8/27

Lloyd's Register  
Foundation

W137-0166

Working pressure by Rules

Combustion chamber plate