

T.S.S. WESTMORELAND  
SPARE GEAR.

11.5.17

State the articles supplied:-

- 1 Set studs and nuts for one propeller blade.
- 1 Propeller shaft. ✓
- 9 Bolts and nuts for screw shaft couplings. ✓
- 50 Condenser tubes.
- 100 Ferrules for ditto.
- 1 Pump rod for air pump.
- 1 Valve chest complete for steam end of air pump.
- 1 Air pump guard and studs.
- 1 Set air pump valves for one head valve of one pump.
- 2 Bolts and nuts, of each size fitted, for turbines and gearing. ✓
- 4 Studs and nuts for air pump glands.
- 1 Feed pump steam valve chest complete.
- 1 Set of main turbine bearing bushes of each size, complete.
- 1 Set of pinion shaft bushes of each size, complete.
- 6 Studs for manhole doors.
- 6 Bolts for condenser doors.
- 6 Studs for air pump covers.
- 1 Set valves for lubricating pumps.
- 1 Set of valves for feed pump, complete. ✓
- 1 Set piston rings for lubricating pumps.
- 2 Filter buckets (Cascade Filter).
- 100 Furnace bars for main boilers.
- 36 Gauge glasses (Adamant).
- 15 Boiler tubes (plain).
- 4 Boiler feed check valves.
- 18 Cast iron baffle plates for furnace fronts.
- 8 Cast iron baffle plates for fire doors.
- 6 Ashpit door handles.
- 4 Ashpit door catches.
- 4 Ashpit door hinges.
- 3 Air valve handles for furnace fronts.
- 4 Fire door handles.
- 4 Fire door catches.
- 24 Mica sight-hole pieces.
- 6 Front bearers, main boilers.
- 2 Ingots white metal.
- 1 Propeller stud template.
- 1 Taper template for boss and keys.
- 1 template for couplings.
- 1 Drawing of propeller and tail shaft.
- 1 Spare circulating pump impeller and shaft.
- 3 M.B. Safety Valve Springs.
- 1 Superheat " " " ✓
- 3 Sets Bilge Pump Valves. ✓
- 3 Plates iron assorted. ✓
- 6 Bars " " ✓
- 12 Brass Bolts. ✓

*Wm. H. Copman.*



© 2020

Lloyd's Register  
Foundation

W138-0056