



Lloyd's Register of Shipping,

31-32, Oxford Street,

Southampton, 22nd September, 1941.

Dear Sir,


In reply to your letter of the 19th instant having reference to the recommendation made in August 1939 to fit a new propeller to the "WALMER CASTLE". The new propeller was intended to replace the broken one removed at that time. The recommendation was made after discussing the matter with the Owner's Representatives who fully concurred, in view of the propeller then fitted having been previously removed on account of damage, and it was the Owners intention at the time to fit a new one at the next dry docking.

So far as we remember the propeller was only damaged at or near the tip of the blades and appeared efficient, although the Pitch had not been checked. If it has given satisfaction over the intervening period we are of the opinion it could be accepted without restriction.

We are, Dear Sir,

Yours faithfully,

The Secretary,
WOKINGHAM.



© 2020

pro The Surveyors.

Lloyd's Register
Foundation

W138-0158

minutes in January 1860

some books 18-18

and

... ..

... ..

... ..

... ..

... ..

... ..

... ..

... ..

... ..

... ..

... ..

... ..

... ..

... ..

... ..

... ..

... ..

... ..

... ..

... ..

... ..

... ..

... ..

H
R
23 SEP 1860

1/11



© 2020
Lloyd's Register
Foundation