

COPY GLASGOW REPORT No. 64316

# Lloyd's Register of Shipping.

95, Bothwell Street, Glasgow, C.2.

9th September, 1941

Dear Sirs,

I beg to acquaint you that the Committee have had before them at their Meeting today the Reports of the Society's Surveyors at Glasgow of their recent survey of the M.V. "WALMER CASTLE".

The Surveyors report that a General Examination of the vessel has been carried out and, in view of the reports now received, I have to state that the Committee have given instructions for a notation of 'Examined 8.41' to be assigned indicating that from the parts now seen, the vessel is considered to be in an efficient condition and that her class will be maintained for twelve months from that date.

I may say that, as previously recommended, the vessel's class is subject to the indented tank top plating in No.2 hold, No.3 keel plate and shell plates A.3 and 4 (P & S), E.6 and F.4, 5 & 8 (S.S.) being dealt with and to a new propeller being fitted at next docking.

I am, Dear Sirs,  
yours faithfully,

Messrs. Union Castle Mail S.S. Co., Ltd.  
Orchard House,  
Blackwall,  
LONDON, E.14.

Secretary to the  
Glasgow Committee.

Lloyd's Register  
Foundation

W138-0165