

+100 A1
5.16.15

+L.M.C.
B&H

TSS 1.
5.

why th

Ind. 12. H.

10

2

Sent to Chief Surveyors

7.10.15

Received from Chief Surveyors 8 DCT 1915

VESSEL'S NAME

Sheess Dolres

Rpt. Rec

No. 1144

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

No. 3

SURVEY PARTLY HELD.

When due

6-14

When proposed to be completed before June 1915, as agreed.

Portion of Survey held, &c.

All held on survey.

The Special Survey No 3, due June 1914 has been partly held

The Bilge Pumpers now state the vessel will shortly arrive at that port when the Survey will be completed.

They add the owners were under the impression the Survey had been completed.

The year of grace expired in June last.

It is submitted action might be deferred until the Survey be completed as now proposed without fail.

H.W. M
8.10.15

To complete Survey — all deck plating, live bunkers must, ~~spare~~ rigging, pumps & plating in way of sidelights to be examined.

Bulk room ceiling & saddle back to be sealed & painted, & an air pipe on port side to be repaired.

Damage or Repair Fee (if any) **200**

Fees applied for
Not yet 19

W1438 - 0013

(per Section 28)

(per Section 28)

Alto

£

Survey, and also
or L.M.C. 9.15

and
to

Lloyd's Register
Foundation