

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 19... When hauled in at Local Office 19... Port of London

No. in Reg. Book. 939 on the Wood, Iron or Steel ss "Etelvina" Master  
Survey held at  
Date, First Survey Last Survey 19  
(No. of Visits)  
Built at Krampien a/d Jael By whom A. J. Otto Jensen When 1910 12  
Owners Cia. Naviera de Cuba Port belonging to  
Owners' Address  
(if not already recorded in Appendix to Register Book).

TONNAGE:-  
GROSS 242  
UNDER DK. 162  
NET 125

Afloat or in Dry Dock? Name of Dock Destined Voyage  
DBorDBa feet; uE&B feet; f feet; }  
city tons. FPT tons; APT tons; MT feet tons. }  
Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).  
CHARACTER, \* for Special Survey, Date of last Survey and of Periodical Survey. Year assigned now required. Machinery and Boiler Surveys (including date of N.B., if any).  
+ 100 A 1. + LMC 2 11  
2 11. TS 4 13

alterations in the existing records should be underlined.  
vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, the inner bottom plating, especially in the boiler space.

Report, No. 672 Port LA

When held, must be reported in detail and serially in the terms of the Rules. State clearly the nature and extent of Examinations and subsequent repairs. Repairs due to other causes; damage (the cause of which must be stated) should be separated from Repairs due to other causes; repairs detailed in the body of the report, should be summarised in the form shown below. Whenever the anchors or Chains is reported, the particulars should be clearly stated in the space provided on form. State also the dates and initials of any letters respecting this case.

Society's Freeboard (if assigned) as painted on Ship and now verified

Where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and why they were not.  
Was a damage report made by anyone else? If so, by whom?

EXAMINATION AS PER RULE, FOR

DAMAGE REPAIRS :—		Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items :—		
Faired or Repaired											
Repaired in place											
CONDITION OF THE		Stringers Inner Bottom Plating State if Tanks have been examined inside State if Tanks now tested Bulkheads Ceiling Cement or Asphalt (State which.) Rudder Steering gear and its connections Windlass Have Pumps now been examined and found efficient? Have Sluice Valves now been examined and found efficient? Have Watertight Doors now been examined and found efficient?					Dblg. Plates under Sounding Pipes Engine Room Skylights Coal Bunkers, Open'gs, Lids, &c. Scuppers Cargo Hatchways Hatches Planking of Wood Vessels Caulking ditto Treenails ditto Breasthooks & Stemson ditto Transoms, Pointers, & Grutches ditto Timbers of Frame at openings ditto Ditto ditto at other places ditto Stringers, Clamps & Shelves ditto Salting ditto (State if examined.)			Copper, or Y.M. of Wood Vessels (State if on Felt.) When put on, Month Year Boats Masts, Yards, &c. Condition, how ascertained (State if wedges removed) Sails Equipment letter Anchors, No. of Cables (State if now ranged) ,, length size (on board) ,, Rule length size Hawser & Warps Standing & Running Rigging	


Observations, Opinion as to Class, Recommendation, &c. :-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon the survey, thus for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey," or "to remain as classed and to have record of survey, 1,15, and the notations of ss No. 1-15 and ptND15, &c."

per Section 88)	£	:	:	Fees applied for,
Age or Repair Fee (if any) (Sec. 88)	£	:	:	19
Expenses (if chargeable)	£	:	:	Received by me,
Second Surveyor's Fee (if any)	£	:	:	19

Surveyor to Lloyd's Register of Shipping.

Committee's Minute  
Character Assigned



© 2021

Lloyd's Register Foundation

W11444-0121

In Certificate required? If so, to be sent to