

22 APR 1914

nt to Chief Surveyors 22. 4. 14

Received from Chief Surveyors

ESSEL'S NAME *Sc N "Flicker"*

Report *Hul*

No. *27380*

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/6/92)

ature of Survey *Screw shaft.*

When due *10. 13.*

The screw shaft became due for survey in October last.

The owners have now informed the Surveyors that they do not wish to continue the vessel's class


Submitted the vessel's class be omitted from the next re-print of the Register Book.

Out Class

T. J. S.

22. 4. 14

ARRJL



© 2021

Lloyd's Register Foundation

W1449-0160

of Wood Vesse
velt.)
month

ined

remove

range

igging.